ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	9	Vidyaranyapura

Street ID	Street Name	Significant Landmark
W0743, W0635, W0470, W0472, W0745, W0747, W0715, W	2nd Main Rd, 8th Crs, 2nd Crs, 3rd Crs, NA, 4th Crs	Virupakshapura

Segment No.	Total Length (m)
9/C-W0743/S082630	404.60

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	194.48	77.574640	13.066482	77.575119	13.068176	W0472	W0422
2	110.35	77.573646	13.066744	77.574613	13.066433	W0715	W0747
3	99.77	77.573386	13.065878	77.573609	13.066744	W0486	W0470

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements and Asphalting to roads at Virupakshapura and surrounding areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka	3000000	2016

Year	Type of Work	Other Work Type
2016 - 2017	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements and Asphalting to roads at Virupakshapura and surrounding areas in Ward no 09 (Vidyaranayapura) Vidyaranayapura Sub-Division Yelahanka zone Modified work	009-16-000004

Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/120/2016-17	31/08/2016	60 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
31/08/2016	30/08/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SURENDRA B.T		0.00

Phone No.	E-Mail ID
9880706343	

Field Inspection Details

Number of Trees	Any Other Information	Name
6		JANARDHAN

Date of Inspection	Remarks
28/10/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	9	Ward Name:	Vidyaranyapura	Street ID:	W0743, W0635, W0470, W0472,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	28/10/2016	27/11/2016	COMPLETED
SE	VASU K M	28/10/2016	27/11/2016	COMPLETED
EE	YARAPPA REDDY	28/10/2016	27/11/2016	COMPLETED
AEE	SHIVAKUMAR	28/10/2016	27/11/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0743, W0635, W0470, W0472,

AE	JANARDHAN	28/10/2016	27/11/2016	COMPLETED
AE	JANARDHAN	28/10/2016	27/11/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 9 **Ward Name:** Vidyaranyapura **Street ID:** W0743, W0635, W0470, W0472,